Community Meeting - Pimpinio 4th March 2019

Officer

Updated 6.5.2019

Item	Referred to	Merit	Additional Notes	Action Status
			Inspect Sampsons Rd, Dahlen Quarry Rd, Wail Polkemmet Rd and nearby roads.	
Deader the constation to the	Labor Manutin	60440	This has been placed on the Rural Roads Pruning Program and we intend to	0
Roads with vegetation issues	John Martin	69448	complete these works by the middle of May.	Open
	Labor Manutin	N./A	Community aiming for this cropping season. An environmental assessment is	0
Roadside cropping opportunities	John Martin	N/A	being obtained.	Open
Thamms Rd and School Rd condition	John Martin	N/A	Assessment planned along with discussion about a cost sharing partnership	Open
Wail Polkemmet Rd	John Martin	69455	Suggestion to grade before winter. Assessment to be completed.	Open
War memorial parking	John Martin	N/A	Request for road base near parking area	Open
-				
Culvert at the corner of Miller and Station Sts	John Martin	69095	Culvert has separated. Inspection required. Pipe could not be located.	Finalised
Town welcome signs	John Martin	69466	Timber needs re-painting. Investigate condition.	Open
			Assesment of lights and repair and clear where necessary. Council Staff have	
			inspected the trees that we maintain and they are not the ones causing the issue.	
			Vicroads has been contacted and an assessment requested. They will inform	
Street lights not working or blocked by limbs	Mark Schirmer	69450	HRCC when works complete.	Open
			obstructing driver vision. Works have been referred to Vicroads for an aborist	
Falling sugar gum limbs	John Martin	69476	inspection on these trees.	Open
Sealing entrance to sport reserve	Alan Clyne	N/A	Inspection to assess current pavement and whether it will hold up to a seal	Open
Five-way intersection at Wail Katyil, Wail Kalkee Rd	Alan Clyne	N/A	Arrange to meet Dale Bartlett at site	Open
Polkemmet Rd bridge trees	John Martin	69104	Obstructing driver vision. <i>Trees have been removed</i> .	Finalised
Rules West Road table drain	John Martin	69127	Tree sapplings growing. Investigation required. Trees have been removed	Finalised
			130 m north of Rules West Rd, on dirt road, shortcut through town (or route for	
			B-doubles to avoid level crossing), a culvert has been pulverised, and there is a	
			bulldust type hole. Often goes under water. Suggest a bit of traffic, needs	
Rules West Road culvert	John Martin	69462	grading more often.	Open
			Identify the location of bus stops. Need for bus stop shelter. PTA responsible for	
Bus stops	John Martin	69494	bus shelters. Will refer to them for investigation	Open
Riggs Road drainage	John Martin		Road needs a cross slope	Open
Curran Road Lighting	John Martin		Corner of Natimuk Road and Curran Road needs improved lighting	Open
Rural Recycling Service	John Martin	N/A	Request for monthly service. John to include in the Waste Strategy.	Open
			Review the agreement with the Pimpinio Uniting Church to determine	
War memorial garden	Susan Surridge	69383	responsibility for the garden watering	Open