	Action		
Item	Status	Task officer	Comments/Follow-up
Black Spot funding for tower to improve coverage in Toolondo	OPEN	Angela Murphy	
House at Clear Lake that burnt down. Query regarding who is			
responsible to clear the site? Does MBS issue an order?	OPEN	Angela Murphy	
			Toolondo Hall and tennis courts sits on Crown Land
Question about landownership of the reserve and whose asset the			managed by DELWP/local committee of
tennis courts are	OPEN	Susan Surridge	management. Email response to query 5/6/2019
Tree overhang on Wades Rd and Elliots Back Lane, Kanagulk. Also			
prolific new growth of red gums on Wades Rd. Inspection requested	OPEN	Moir Rob	
Request for central white line around bends on Telangatuk East-	OPEN	Moir Rob	
Rough section of Jallumba Mockinya Road near Hutchinsons Road to the			
west about 3/4 km. Road shoulders are bad 1km south of Jallumba	OPEN	Moir Rob	
mproved signage on Wonwondah-Toolondo Road to direct people to	OPEN	Moir Rob	
Trees at Nurrabiel '5 way' intersection need pruning to improve			
visability up Little Mallee Road. Inspection requested	OPEN	Moir Rob	
Trees on Wonwondah-Toolondo Road , need envelope clearance just			
east of channel and also 2km east of Toolondo intersection. Inspection	OPEN	Moir Rob	
Request for kangaroo signs on Telangatuk East Rocklands Rd at Wash			
Tomorrow Swamp, from north of transfer station through to John	OPEN	Moir Rob	
Fallen limbs on track near the shed at the old Toolondo school.	OPEN	Moir Rob	
Wash Tomorrow Road is in poor condition, has large trees that need			
trimming and the road signposted. Inspection requested	OPEN	Moir Rob	
Tree limbs on Clear Lake Road right at the old school in Clear Lake and			
on Bow Lake Road. Inspection requested	OPEN	Moir Rob	
Request for culvert on Nurrabiel Church Road about 400-600m east of			
Nurrabiel Cemetery road. Inspection requested	OPEN	Moir Rob	
Suggestion for culvert on Wonwondah Toolondo Road, 1020m south of			
Nurriabel Church Road. Table drain is full of trees in this section.	OPEN	Moir Rob	
Entrance to the Toolondo Golf Course can be dangerous. Has blind			
spot. Can speed restrictions be considered?	FINALISED	Moir Rob	
Signs on chanel bridges - need re-alignment to reduce glare to drivers	OPEN	Moir Rob	